

Photos of 2005 Gulf Coast Disaster Debris Management *Drywall Photos*

Timothy G Townsend, PhD, PE
Professor of Environmental Engineering Sciences
Engineering School of Sustainable Infrastructure and Environment
<http://townsend.essie.ufl.edu>



Disaster debris is piled on the right-of-way for pickup. This photo is building materials supply business. New sheets of gypsum drywall were damaged as a result of the storm.

Debris piled on right-of-way





In flooded houses that can be salvaged,
drywall must be removed.

**HOUSE CLEAN-UP
&
DRYWALL
REMOVAL**
(504) 554-0681



Drywall and carpet removed
from flood damaged house





Inside of building after drywall has been removed

Photos of 2005 Gulf Coast Disaster Debris Management *Drywall Photos*

Timothy G Townsend, PhD, PE
Professor of Environmental Engineering Sciences
Engineering School of Sustainable Infrastructure and Environment
<http://townsend.essie.ufl.edu>